State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt
Governor

355 We

Ted Stewart Executive Director James W. Carter

Division Director

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 801-538-5340 801-359-3940 (Fax)

801-538-5319 (TDD)

Partial: X Complete: Exploration: Inspection Date & Time: 9/14/93 1:00 TO 2:00
Date of Last Inspection: 8/10/93

County: Emery Permit Number: ACT/015/025 Mine Name: Bear Canyon Mine Permittee and/or Operator's Name: Co-Op Mining Company Business Address: P.O. Box 1245, Huntington, Utah 84528 Type of Mining Activity: Underground X Prep. Plant___ Surface Other State Officials(s): Susan White Company Official(s): Charles Reynolds Federal Official(s):_ Weather Conditions: fair and cool Existing Acreage: Permitted-1060 Disturbed-24 Regraded-___ Seeded-___ Bonded-24 Increased/Decreased: Permitted-___ Disturbed-___ Regraded-___ Seeded-___ Bonded-___ Status: __Exploration/__Active/__Inactive/__Temporary Cessation/__Bond Forfeiture Reclamation (Phase I/Phase II/Final Bond Release/Liability REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS Instructions

1. Substantiate the elements on this inspection by checking the appropriate performance standard.

a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.

b. For partial inspections check only the elements evaluated.

- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
 Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[]	П		
2.	SIGNS AND MARKERS	X	$\overline{\Box}$	\Box	$\overline{\square}$
3.	TOPSOIL	$\overline{[X]}$	$\overline{\Box}$	$\overline{[X]}$	$\overline{\square}$
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[X]		[X]	\Box
b.	SEDIMENT PONDS AND IMPOUNDMENTS	$\overline{[X]}$	$\overline{\Box}$	[X] [X]	\Box
c.	OTHER SEDIMENT CONTROL MEASURES	<u>[]</u>		$\overline{\square}$	Ll
d.	WATER MONITORING			$\overline{\square}$	\Box
e.	EFFLUENT LIMITATIONS	<u> </u>	\Box	$\overline{\square}$	\Box
5.	EXPLOSIVES	口	$\overline{\Box}$	\Box	ΞĨ
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES			口	ΞĪ
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS		$\overline{\Box}$	\Box	ΞĪ
8.	NONCOAL WASTE	ĪĪ	$\overline{\Box}$	$\overline{\square}$	ΞĪ
9.	PROTECTION OF FISH, WILDLIFE AND	 -			
	RELATED ENVIRONMENTAL VALUES		\Box	\Box	\Box
10.	SLIDES AND OTHER DAMAGE		$\overline{\Box}$	$\overline{\square}$	\Box
11.	CONTEMPORANEOUS RECLAMATION	\Box	\Box	\Box	<u>[_]</u>
12.	BACKFILLING AND GRADING	\Box		\Box	\Box
13.	REVEGETATION	\Box		\Box	\Box
14.	SUBSIDENCE CONTROL	\Box	\Box	\Box	
15.	CESSATION OF OPERATIONS	\Box	\Box	\Box	Ĺl
16.	ROADS:				
a.		\Box	\Box	\Box	\Box
	DRAINAGE CONTROLS		\Box		\Box
17.	OTHER TRANSPORTATION FACILITIES	\Box	\Box		\Box
18.			\Box	\Box	\Box
19.	AVS CHECK (4th Quarter-April, May, June)(date	e)			\Box
20.	•	\Box	\Box		\Box
21.	BONDING & INSURANCE	-F-1	f 1	r 1	f 1

INSPECTION REPORT

(Continuation sheet)

Page _2_ of _2_

PERMIT NUMBER: ACT/015/025

DATE OF INSPECTION: 9/14/93

(Comments are Numbered to Correspond with Topics Listed Above)

3. TOPSOIL

The berm around the shower house topsoil pile was in place.

4. HYDROLOGIC BALANCE:

Two water user groups had protested the public notice given by the operator to mine the tank seam. The Division held a public hearing on September 9, 1993 and the water users issues were heard. To date the Division has not issued a finding.

Diversions -

Ditch D-1U requires maintenance while still in compliance.

Culvert C-2U had been crush and had been replaced with a steel pipe.

Piping was noted around flex culvert C-8U prior to the culvert running underneath the coal storage pad on the last inspection. The operator regraded around the base of the culvert so that water would not stand and seep under the inlet.

Undisturbed and disturbed drainage ditch D-8U and D-9U had been installed and N93-35-7-3 had been abated prior to this inspection.

N93-35-5and 6 have had the required plans submitted to the Division. Upon Division approval the plans will be implemented so the violations can be abated.

Sediment ponds and impoundments -

N93-35-7-3 was abated prior to this inspection and Pond C was completed.

Cleaning of Pond A had just begun at the time of this inspection.

Copy of this Report:

Mailed to: Bernie Freeman (OSM), Wendell Owen (Co-Op)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: Wexas White #35 Date: 9/16/93